Oil Field Environmental Incident Summary

Responsible Party: Buckhorn Energy Services, LLC

Well Operator: BUCKHORN ENERGY SERVICES, LLC

Well Name: VINGER 1

Field Name: WHEELOCK Well File #: 90212

Date Incident: 7/21/2014 Time Incident: 01:00 Facility ID Number:

County: WILLIAMS Twp: 156 Rng: 98 Sec: 21 Qtr: SE SE

Location Description:

Submitted By: Nancy Roberts Received By:

Contact Person: Nancy Roberts

PO BOX 630530

LITTLETON, CO 80163

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units	
Oil	4	Barrels	4	Barrels	4	barrels	
Brine	2	Barrels	2	Barrels	2	barrels	

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 1/13/2017 Clean Up Concluded: 7/23/2014

Risk Evaluation:

none

Areal Extent:

Potential Environmental Impacts:

Only impact was to soil in facility berm area immediately around tank.

Action Taken or Planned:

Additional training of the site operator will be conducted to ensure that this does not happen again.

Wastes Disposal Location: Spill was picked up and returned to the fluid stream.

Agencies Involved:

Updates

Date: 7/27/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank overflow, remained on location, within the diking, according to the report. NDIC retains oversight.